

Care and Maintenance



GĒOS Sustainable Surfaces are very easy to maintain. The recycled glass used in GĒOS Sustainable Surfaces, coupled with high performance, stain resistant polymers, results in a durable, non-porous, chemical resistant surface. GĒOS Sustainable Surfaces are also heat and scratch resistant, but not heat and scratch proof. The use of trivets or hot pads are recommended with hot pots and a cutting board is recommended when using a knife or sharp instruments on GĒOS Sustainable Surfaces.

GĒOS Sustainable Surfaces keep their brilliant gloss and superior smooth surface without polishing. Because it is non-porous, GĒOS Sustainable Surfaces do not require sealants or waxes.

GEOS Sustainable Surfaces also give you peace of mind. In the unlikely event that you do experience any problems due to a manufacturer's defect, you can rest assured that EOS Surfaces LLC backs GEOS Sustainable Surfaces with a 10-year limited warranty.

Routine Care

With simple care, GEOS Sustainable Surfaces will retain its deep, lustrous appearance for many years. For routine cleaning, use a damp cloth or paper towel and, if necessary, a small amount of non-bleach, non-abrasive cleanser.

Even though GEOS Sustainable Surfaces resist permanent staining when exposed to liquids, it is advisable to wipe up food and liquid spills as soon as possible.

For stubborn or dried-on spills, use a non-abrasive cleaning pad such as a white 3M Scotch-Brite® pad along with Formula 409® Glass and Surface Cleaner or comparable cleaning product.

Avoid cleansers that contain bleach.

Preventing Heat Damage

To maintain the beauty and structure of GEOS Sustainable Surfaces, do not place hot skillets, crock pots, or roasting pans directly onto the surface. EOS Surfaces LLC recommends the use of trivets and hot pads.







ELITE GLOBAL

